




Ironing Instructions


Beads should be fused together with a **dry** household iron by an **adult** only. Please keep children at a safe distance.

1. Place pegboard on flat, heat-safe surface.
2. Set iron to medium. Place ironing paper over beads and pegboard. Using a circular motion, iron for about 10-20 seconds. Do not press down on the iron. When ironed properly, beads will still have an open center. Let cool.
3. Remove ironing paper and bead design from pegboard. Flip design over to expose the non-fused side. Place ironing paper over design and iron again. To prevent bead design from warping, place a heavy book on design as it cools.









Note: Do not place iron directly against beads or pegboard. Pegboard is not designed for use in any type of oven; it will warp.

Pegboard and ironing paper are reusable.






Liberty Crown and Torch




- | | | | | | | | | |
|-----------|---|-------|-----------|---|------|-------|---|------|
| Lt. Green |  | x 956 | Yellow |  | x 24 | Brown |  | x 8 |
| Lagoon |  | x 240 | Cheddar |  | x 43 | Black |  | x 45 |
| Mint |  | x 185 | Lt. Brown |  | x 46 | | | |


4 Large Interlocking Pegboards

Left Side







Right Side





Torch Assembly



Wear and Celebrate!